Optional Accessories

- 07GZA000: Scriber
- 953638: Holding bar for test indicator (length: 50 mm)
 900209: Holding bar for test indicator (length: 100 mm)
 953639: Holding bar for test indicator (length: 2 in)
 900306: Holding bar for test indicator (length: 4 in)

- 900306: Holding bar for test indicator (length. 4 III)
 900321: Swivel clamp used with holding bar (metric)
 900322: Swivel clamp used with holding bar (inch)
 902053: Clamp (with doverail groove, ø6 and ø8 holes)
 Note: A test indicator can be mounted on a height gage using a holding bar and clamp.

Dial Height Gage SERIES 192 — With digital counter

• Easy and error-free reading with both up and down digital counters as well as a dial.



• Can be zero-set at any arbitrary position.

• Provided with a large adjustment wheel for easy height adjustment.

• Clamp can be operated easily and securely.



• Carbide tipped scriber (07GZA000) is attached as standard. (Standard accessory: Scriber clamp **05GZA033**)

• Fits comfortably in the hand and moves easily

• For precision Black Granite Surface Plates, refer to page E-49.

Note: Do not hold the height gage by the column as this can affect the accuracy.



SPECIFICATIONS

Metric								
Order No.	Range (mm)	Graduation (mm)	Maximum Permissible Error* (mm)/EMPE	Height (mm)	Mass (kg)			
192-130	0 - 300	0.01	±0.03	470	4.2			
192-131	0 - 450		±0.05	648	9.2			
192-132	0 - 600			798	9.8			
192-133	0 - 1000		±0.07	1220	17.0			

* Maximum Permissible Error, EMPE, is the term (notation) used in JIS B 7517: 2018, revised based on ISO/TR 14253-6: 2012.

192-130

Inch					
Order No.	Range (in)	Graduation (in)	Maximum Permissible Error* (in)/EMPE	Height (mm)	Mass (kg)
192-150	0 - 12	0.001	±0.0015	470	4.2
192-151	0 - 18		±0.002	648	9.2
192-152	0 - 24			798	9.8
192-153	0 - 40		±0.003	1220	17.0

* Maximum Permissible Error, EMPE, is the term (notation) used in JIS B 7517: 2018, revised based on ISO/TR 14253-6: 2012.

DIMENSIONS



